

ABSTRACT

WA-II-154

Early 19th Century

Stuccoed Stone Farmhouse

Hagerstown Vicinity

private

This farm complex which includes a stuccoed stone house, a frame bank barn and other frame outbuildings is an example of a 19th century rural group. The house shows evidence of having been built during the early 19th century and of having had renovations during the later 19th and 20th centuries. The stuccoed surface of the stone house was not an uncommon treatment in this region during the 19th century. The outbuildings appear newer than the house.

MARYLAND HISTORICAL TRUST

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC

AND/OR COMMON

Stuccoed Stone Farmhouse

2 LOCATION

STREET & NUMBER

Route 66, South of Mt. Aetna

CITY, TOWN

☒ VICINITY OF Hagerstown

CONGRESSIONAL DISTRICT

6

STATE

Maryland

COUNTY

Washington

3 CLASSIFICATION

CATEGORY

☐ DISTRICT☒ BUILDING(S)☐ STRUCTURE☐ SITE☐ OBJECT

OWNERSHIP

☐ PUBLIC☒ PRIVATE☐ BOTH

PUBLIC ACQUISITION

☐ IN PROCESS☐ BEING CONSIDERED

STATUS

☒ OCCUPIED☐ UNOCCUPIED☐ WORK IN PROGRESS

ACCESSIBLE

☐ YES: RESTRICTED☐ YES: UNRESTRICTED☒ NO

PRESENT USE

☒ AGRICULTURE☐ COMMERCIAL☐ EDUCATIONAL☐ ENTERTAINMENT☐ GOVERNMENT☐ INDUSTRIAL☐ MILITARY☐ MUSEUM☐ PARK☒ PRIVATE RESIDENCE☐ RELIGIOUS☐ SCIENTIFIC☐ TRANSPORTATION☐ OTHER**4 OWNER OF PROPERTY**

NAME

Vaughn H. Dullabaun, et al

Telephone #:

STREET & NUMBER

Route # 1, Box 184

CITY, TOWN

Hagerstown

VICINITY OF

STATE, zip code

Maryland 21740

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE,

REGISTRY OF DEEDS, ETC.

Washington County Court House

STREET & NUMBER

West Washington Street

CITY, TOWN

Hagerstown

STATE

Maryland 21740

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

Maryland Historical Trust Survey #3019

DATE

Summer 1967

☐ FEDERAL ☒ STATE ☐ COUNTY ☐ LOCALDEPOSITORY FOR
SURVEY RECORDS

Maryland Historical Trust

CITY, TOWN

Annapolis

STATE

Maryland 21401

7 DESCRIPTION

WA-II-154

CONDITION		CHECK ONE	CHECK ONE
<input type="checkbox"/> EXCELLENT	<input checked="" type="checkbox"/> DETERIORATED	<input type="checkbox"/> UNALTERED	<input checked="" type="checkbox"/> ORIGINAL SITE
<input type="checkbox"/> GOOD	<input type="checkbox"/> RUINS	<input checked="" type="checkbox"/> ALTERED $\leq 50\%$	<input type="checkbox"/> MOVED DATE _____
<input type="checkbox"/> FAIR	<input type="checkbox"/> UNEXPOSED		

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

This farm complex is located at the end of a private lane which extends in a westerly direction from Maryland Route 66 just south of Mt. Aetna, southeast of Hagerstown in Washington County, Maryland. The buildings are situated on a ridge and face east, overlooking Beaver Creek, at this point quite small, and Maryland Route 66.

The house is a two story five bay stone structure sheathed with stucco. An arch topped date stone is located in the south gable, but no inscription could be seen on it.

Windows and doors appear to be aligned with each other in the walls. Most windows have narrow frames finished with a bead at the inside edge. These may be replacements since they do not match the door frames which are quite wide with joints secured with wooden pegs. First floor windows have nine over six pane sashes while upper story windows have six over six sashes.

The original principal facade appears to have been the east elevation. Now, however, the main entrances are in the west wall, where doors are located at both the first and second story levels. Patching of the masonry around the upper level doors suggests that alterations were made there. These doors do not have transoms.

Sheet metal covers the roof of the house and brick chimneys are located inside the end walls with a third chimney extending from the interior of the house near its center.

Just to the south is a frame bank barn. East of it is a frame hog barn with a large semi-circular fan light in its south gable. This architectural element was presumably reused from another structure. The property contains 103.396 acres. The buildings are in deteriorated to fair condition.

CONTINUE ON SEPARATE SHEET IF NECESSARY

8 SIGNIFICANCE

PERIOD		AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW			
<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION	
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE	
<input type="checkbox"/> 1500-1599	<input checked="" type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE	
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN	
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER	
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION	
<input type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)	
		<input type="checkbox"/> INVENTION			

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

This farm complex which includes a stuccoed stone house, a frame bank barn and other frame outbuildings is an example of a 19th century rural group. The house shows evidence of having been built during the early 19th century and of having had renovations during the early 19th or 20th centuries. The stuccoed surface of the stone house was not an uncommon treatment in the region during the 19th century. The outbuildings appear newer than the house.

CONTINUE ON SEPARATE SHEET IF NECESSARY

MAJOR BIBLIOGRAPHICAL REFERENCES

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATAACREAGE OF NOMINATED PROPERTY 103.396 acres

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE

COUNTY

STATE

COUNTY

11 FORM PREPARED BY

NAME / TITLE

Paula Stoner Dickey, Consultant

ORGANIZATION

Washington County Historical Sites Survey

DATE

February 1978

STREET & NUMBER

County Office Building, 33 West Washington Street

TELEPHONE

791-3065

CITY OR TOWN

Hagerstown

STATE

Maryland 21740

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438

FUNKSTOWN QUADRANGLE

MARYLAND WASHINGTON CO.

7.5 MINUTE SERIES (TOPOGRAPHIC)

SW/4 HAGERSTOWN 15' QUADRANGLE

5463 HHC
(SMITH-DURGO)

271 40'


272

273 520 000 FEET

274

77°37'30"

39°37'30"



WA-II-154

WA-II-153

WA-II-147

4386

4385

35'

4384



100-154
100-154
100-154
Stuccoed Stone Farmhouse

Route 66, south of Mt. Aetna
Hagerstown Vicinity

PAULA STONER DICKEY
CONSULTANT, WASHINGTON CO
HISTORICAL SITES SURVEY



1700
1975

Stuccoed Stone Farmhouse

**Route 66, south of Mt. Aetna
Hagerstown Vicinity**

PAULA STONER DICKEY
CONSULTANT, WASHINGTON Co.
HISTORICAL SITES SURVEY



11/20/73
Nov. 73
Stuccoed Stone Farmhouse

**Route 66, South of Mt. Aetna
Hagerstown Vicinity**

PAULA STONER DICKEY
CONSULTANT, WASHINGTON CO.
HISTORICAL SITES SURVEY